




F | G | 2







107A 101 103B 4 305 103C 115 9

4/14

F I G. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9





FIG. 10



[] THE STATE OF TH

FIG. 11

URL http:/	//www.maintain.co.jp/db/input.html	
I KOUBLE (DB INPUT WINDOW	
	-	
1 00001 TENOE BITTE (EUOFO) TO		
SUBJECT	OPERATING ERROR (START-UP ERROR) ~403	
SERIAL NU	MBER S/N 465NS4580001 ~402	
DEGREE OF URGENCY D ~405		
SYMPTOM	LED IS KEPT FLICKERING AFTER 企	
18	POWER-ON	
DEMEDY		
HEMEDI	ADDECC DED DITTON IN ACTIVATIONS	
	(
PROGRESS		
	408	
	LED IS KEPT FLICKERING AFTER POWER-ON 406 POY POWER ON AGAIN (PRESS RED BUTTON IN ACTIVATION) RESS INTERIM HAS BEEN DONE 408 PORESET 410 411 412	
LINK TO R	REMEDY POWER ON AGAIN (PRESS RED BUTTON IN ACTIVATION) PROGRESS INTERIM HAS BEEN DONE SEND RESET 410 LED IS KEPT FLICKERING AFTER 406 406 407 407 407 408	

F I G. 12





FIG. 13



103B 11è9 (305 (1167 | 115 | 1169

14/14